

WASHINGTON D.C. 20554

TTY (202) 418-2555

News media information 202-418-0500
Internet: http://www.fcc.gov (or ftp.fcc.gov)

DA No.

Report No. SAT-00755

Friday February 4, 2011

11-208

POLICY BRANCH INFORMATION

Actions Taken

The Commission, by its International Bureau, took the following actions pursuant to delegated authority. The effective date of these actions is the release date of this Notice, except where an effective date is specified.

SAT-STA-20110118-00014 E S2358 LightSquared Subsidiary LLC

Special Temporary Authority

Grant of Authority Effective Date: 02/02/2011

On Feburary 2, 2011, the Satellite Division granted, with conditions, special temporary authority to LightSquared Subsidiary LLC, for a period of 30 days, to continue to conduct in-orbit testing of the SkyTerra-1 space station at the 101.3° W.L. orbital location in the 1525-1544/1545-1559 MHz, 10.7-10.95 GHz, and 11.2-11.45 GHz bands (space-to-Earth) and 1626.5-1645.5/1646.5-1660.5 MHz (Earth-to-space) frequency bands. For purposes of this temporary authorization, the Satellite Division waived the power flux density limits in Section 25.208(b) of the Commission's rules.

SAT-STA-20110126-00016 E S2387 Intelsat License LLC

Special Temporary Authority

Grant of Authority Effective Date: 01/31/2011

On January 31, 2011, the Satellite Division granted, with conditions, special temporary authority to Intelsat License LLC (formerly PanAmSat Licensee Corp.), for a period of 7 days, to operate the communications payload on the Galaxy 15 space station in the 3700-4200 MHz (space-to-Earth) and 5952-6425 MHz (Earth-to-space) frequency bands at the 93.0° W.L. orbital location to conduct in-orbit testing.

SAT-STA-20110127-00017 E S2387 Intelsat License LLC

Special Temporary Authority

Grant of Authority Effective Date: 02/01/2011

On February 1, 2011, the Satellite Division granted, with conditions, special temporary authority to Intelsat License LLC (formerly PanAmSat Licensee Corp.) for a period of 30 days to continue to conduct telemetry, tracking, and telecommand operations with the Galaxy 15 space station outside the +/-0.05° east/west station-keeping box previously authorized for Galaxy 15.

For more information concerning this Notice, contact the Satellite Division at 202-418-0719; TTY 202-418-2555.